ID	ISSUES-CATEGORY	PRIORITY	IMAGE	OBSERVATIONS	STATUS	CUSTOMER FEEDBACK
1	PACKAGE MISMATCH	CRITICAL		AS PER PART NO IT IS SMD CONNECTOR , IN BOARD WE OBSERVED THROUGH HOLE CONNECTOR. KINDLY CHECK AND UPDATE	OPEN	
2	PIN COUNT MISMATCH	CRITICAL	ground ground ground ground ground ground	AS PER PART NO COMPONENT IS HAVING 3 PIN. IN FOOTPRINT GROUND PAD IS MISSED. KINDLY CHECK AND UPDATE	OPEN	
3	PIN 1 MARKING MISMATCH	CRITICAL	Obidi Nating A Mil Final Paper  5	PIN 1 MARKING FOR THE FOOTPRINT NOT MATCHING WITH THE DATASHEET. KINDLY CHECK	OPEN	
4	COMPONENTS OVERLAPPING	CRITICAL	11	COMPONENTS ARE OVERLAPPING MAINTAIN 20 MIL SPACING BETWEEN COMPONENT TO COMPONENT.	OPEN	
5	SOLDER PASTE	CRITICAL		SOLDER PASTE IS MISSED FOR THERMAL PAD KINDLY CHECK AND UPDATE	OPEN	
6	PIN TO PAD MISMATCH	НОТ	0.3 0.0110 0.45 0.0177 1.25 0.0254 1.25 0.0254	PAD LENGTH IS TOO BIG, KINDLY MODIFY THE FP AS PER DATA SHEET. BIGGER PADS CAN CREATE SOLDER BALLS/MISSALIGNMENT IN ASSEMBLY.	OPEN	
7	COMPONENT TO CONVEYED EDGE SPACING	WARM	X1	COMP TO CONVEYED EDGE SPACING IS 41 MIL FOUND AT Y1. MAINTAIN 125 MIL SPACING FROM CONVEYED EDGE OR PROVIDE HANDLING AREA.	OPEN	
8	TESTPOINTS TOO CLOSE TO EXPOSED COPPER	CRITICAL		TESTPOINTS TOO CLOSE TO EXPOSED COPPER MAY CAUSE ERRORS AT TEST, KINDLY CHECK	OPEN	

ID	ISSUES-CATEGORY	PRIORITY	IMAGE	OBSERVATIONS	STATUS	CUSTOMER FEEDBACK
9	PIN TAIL LENGTH	CRITICAL	(9.41) (2.20) (2.20) -3 (1)	PIN TAIL LENGTH IS 2.29MM AND BOARD THICKNESS IS 1.78MM. PIN PROJECTION IS ONLY 0.5MM. THAT IS NOT SUFFICIENT FOR SOLDERING CONFIRM ONCE.	OPEN	
10	MISSING HOLES	CRITICAL		PIN COUNT MISMATCH OBSERVED IN THE DESIGN KINDLY CHECK, COMPONENT CAN NOT BE MOUNTED.	OPEN	
11	TEST POINTS	CRITICAL		TESTPOINTS CANNOT BE COVERED BY COMPONENTS, KINDLY CHECK	OPEN	
12	DIFFERENT TRACE WIDTHS CONNECTING PADS	нот		DIFFERENT TRACE WIDTHS CONNECTING PADS / SMALL PIN AREA - PAD AREA MAX- CAN CAUSE TOMBSTONING, KINDLY CHECK	OPEN	
13	SILK SCREEN CLEANUP	нот	TP36 1250 144	SILK SCREEN CLEAN UP IS NOT PROPER KINDLY CHECK.	OPEN	
14	COMPONENTS WITH MISPLACED REFERENCE	CRITICAL	C1.54  C1.53  R1.36 =	COMPONENTS WITH MISPLACED REFERENCE DESIGNATORS ON THE SILKSCREEN CAN CAUSE ERRORS AT RE-WORK	OPEN	
15	DRILL SIZE MISMATCH	CRITICAL	The second secon	AS PER DATASHEET RECOMMENDED DRILL SIZE IS 0.4MM WHERE AS IN BOARD IT IS 0.3MM.PLEASE VERIFY THE FOOTPRINT	OPEN	
16	COPPER CONNETION	нот	R4	SMD PADS ARE DIRECTLY CONNECTED TO COPPER, KINDLY CONNECT WITH THERMALS SPOKESTO GET BETTER SOLDERABILITY	OPEN	

ID	ISSUES-CATEGORY	PRIORITY	IMAGE -	OBSERVATIONS	STATUS	CUSTOMER FEEDBACK
17	PLACEMENT ISSUE	CRITICAL	Total City City City City City City City City	AS PER DATA SHEET PLACEMENT OF THE CONNECTOR FROM BOARD EDGE IS 1.45MM, BUT IN DESIGN WE OBSERVED 2.38MM AT J7.J7 AND J8 BOTH ARE SAME CONNECTORS BUT PLACED DIFFERENTLY.	OPEN	
18	FINE PITCH COMPONENT	нот	R203	KINDLY PROVIDE LOCAL FIDUCIALS FOR FIINE PITCH COMPONENTS IT WILL HELP DURING ASSEMBLY.	OPEN	
19	LARGE PIN AREA	нот		LARGE PIN AREA / PAD AREA MAX - LEADS TO POOR SOLDERING (POOR CONNECTIVITY)	OPEN	
20	BOM/AVL VALIDATION	CRITICAL	The Control of the Co	FIND DISCREPANCIES BETWEEN CAD BOM AND MANUFACTURING BOM IDENTIFY ALTERNATE SUPPLIER FORM AND FIT ISSUES	OPEN	
21	SOLDER PASTE	CRITICAL		MISSING SOLDERPASTE MAY RESULT IN BROKEN NET CONNECTIVITY.KINDLY CHECK ANED UPDATE	OPEN	
22	VIAS DRILLED THROUGH SMD	CRITICAL		VIAS DRILLED THROUGH SMD PADS CAN CAUSE SOLDERING PROCESS RELATED ISSUES, KINDLY CHECK.	OPEN	